

Adv: 107 MARK WILSON	Tag M231	License GMW 4597	1G1YY22G7 25134231	Page 1	Invoice C15438
----------------------	----------	------------------	--------------------	--------	----------------

Estimate		Driver/Owner Information			
CAMPBELL, BERNARD		CAMPBELL, BERNARD			
For Office Use		Vehicle Information			
Odometer in: 138550	Out:	Dist: 000 CUS C	Estim	02 CHEVROLET CORVETTE 2DR CPE BLUE	
Begin: 01/28/16		Invoiced: 02/03/16 15:01: MW	Inservice: 08/16/02		

Selected Items * Other Charges may Exist

Concern 01	COURTESY LOANER REQUESTED - MUST BE 21	Operation	Tech	Amount
Type: C		LOANER		
		<u>Subtotal</u>		
		TOTAL CHARGE FOR CONCERN		0.00
Concern 02	MULTI-POINT INSPECTION	Operation	Tech	Amount
Type: C		MPI		
		<u>Subtotal</u>		
		TOTAL CHARGE FOR CONCERN		0.00
Item +03	THREE PART FUEL INJECTION SERVICE	Operation	Tech	Amount
Correction	POWER FLUSH FUEL INJECTORS, CLEAN THROTTLE BODY AREA AND IAC	14G	207 *	114.00
Comment	INSTALL TECH 2 TO COMPUTER AND CHECK FOR TROUBLE CODES. PASSAGE WITH AIR INTAKE CLEANER, ADD FUEL SUPPLEMENT TO FUEL TANK Tech 207 HABIGER, JAY			
Type: C	Line Flags: NOS	<u>Subtotal</u>		
		LABOR-MECHANICAL		114.00
		TOTAL CHARGE FOR CONCERN		114.00
Concern 51	CUSTOMER STATES TURN SIGNAL INOP, CAN HIT A BUMP THEN THEY WILL WORK	Operation	Tech	Amount
51-1	P/A HAZARD FLASHER-FAULTY CAUSING CONCERN		207	322.99
Parts	Part Number PO# Note Description	Qty	Sell	
	000 010359036 SWITCH	1	46.78	46.78
	Tech 207 HABIGER, JAY			
Type: C		<u>Subtotal</u>		
		PARTS		46.78
		LABOR-MECHANICAL		322.99
		TOTAL CHARGE FOR CONCERN		369.77
Concern 52	CUSTOMER STATES HORN INOP	Operation	Tech	Amount

Invoice to: CAMPBELL, BERNARD	Driver/Owner: CAMPBELL, BERNARD
--------------------------------------	----------------------------------------

Invoiced: 02/03/16 15:01:28 MW	02 CHEVROLET CORVETTE 2DR CPE BLUE
--------------------------------	------------------------------------

52-1	P/A HIGH AND LOW NOTE HORN KIT-HORNS FAULTY	207		189.99																												
Parts	<table style="width:100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">Part Number</th> <th style="text-align: left;">PO#</th> <th style="text-align: left;">Note</th> <th style="text-align: left;">Description</th> <th style="text-align: right;">Qty</th> <th style="text-align: right;">Sell</th> <th style="text-align: right;"></th> </tr> <tr> <td>000 089046917</td> <td></td> <td></td> <td>HORN KIT</td> <td style="text-align: right;">1</td> <td style="text-align: right;">84.49</td> <td style="text-align: right;">84.49</td> </tr> <tr> <td>000 089046916</td> <td></td> <td></td> <td>HORN KIT</td> <td style="text-align: right;">1</td> <td style="text-align: right;">84.49</td> <td style="text-align: right;">84.49</td> </tr> <tr> <td colspan="7">Tech 207 HABIGER, JAY</td> </tr> </table>	Part Number	PO#	Note	Description	Qty	Sell		000 089046917			HORN KIT	1	84.49	84.49	000 089046916			HORN KIT	1	84.49	84.49	Tech 207 HABIGER, JAY									
Part Number	PO#	Note	Description	Qty	Sell																											
000 089046917			HORN KIT	1	84.49	84.49																										
000 089046916			HORN KIT	1	84.49	84.49																										
Tech 207 HABIGER, JAY																																
Type: C			Subtotal																													
			PARTS	168.98																												
			LABOR-MECHANICAL	189.99																												
			TOTAL CHARGE FOR CONCERN	358.97																												
Concern 53	CUSTOMER STATES WHILE DRIVING SERVICE ACTIVE HANFLING AND ABS LIGHTS CAME ON, BRAKES APPLIED ON DRIVERS SIDE	Operation	Tech	Amount																												
53-1	HAS CODE C1282 NEEDS YAW RATE SENSOR & BRACKET REPLACED BRACKET #10409133		225	459.99																												
Parts	<table style="width:100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">Part Number</th> <th style="text-align: left;">PO#</th> <th style="text-align: left;">Note</th> <th style="text-align: left;">Description</th> <th style="text-align: right;">Qty</th> <th style="text-align: right;">Sell</th> <th style="text-align: right;"></th> </tr> <tr> <td>000 * 025737829</td> <td></td> <td>INSF</td> <td>*SENSOR</td> <td style="text-align: right;">1 S</td> <td style="text-align: right;">438.67</td> <td style="text-align: right;">438.67</td> </tr> <tr> <td colspan="7">Tech 225 WALLACE, LUCIAN</td> </tr> </table>	Part Number	PO#	Note	Description	Qty	Sell		000 * 025737829		INSF	*SENSOR	1 S	438.67	438.67	Tech 225 WALLACE, LUCIAN																
Part Number	PO#	Note	Description	Qty	Sell																											
000 * 025737829		INSF	*SENSOR	1 S	438.67	438.67																										
Tech 225 WALLACE, LUCIAN																																
Type: C			Subtotal																													
			PARTS	438.67																												
			LABOR-MECHANICAL	459.99																												
			TOTAL CHARGE FOR CONCERN	898.66																												
Concern 54	CUSTOMER STATES IN PARK OR WORSE IN DRIVE AT IDLE, WEIRDIDLE SEE MARK	Operation	Tech	Amount																												
54-1	P/A SPARK PLUGS (8), P/A SPARK PLUG WIRES-TO START-OVERDUE FOR REPLACEMENT-FOUND SPERATIC MISFIRES. ADDRESSED A COUPLE AND BELIEVE THIS REPAIR WILL CORRECT-TO START		207	189.99																												
Parts	<table style="width:100%; border-collapse: collapse;"> <tr> <th style="text-align: left;">Part Number</th> <th style="text-align: left;">PO#</th> <th style="text-align: left;">Note</th> <th style="text-align: left;">Description</th> <th style="text-align: right;">Qty</th> <th style="text-align: right;">Sell</th> <th style="text-align: right;"></th> </tr> <tr> <td>000 019299585</td> <td></td> <td></td> <td>SPARK PLU</td> <td style="text-align: right;">8 S</td> <td style="text-align: right;">7.25</td> <td style="text-align: right;">58.00</td> </tr> <tr> <td>000 088862458</td> <td></td> <td>INSF</td> <td>*WIRE KIT</td> <td style="text-align: right;">1</td> <td style="text-align: right;">126.99</td> <td style="text-align: right;">126.99</td> </tr> <tr> <td colspan="7">Tech 207 HABIGER, JAY</td> </tr> </table>	Part Number	PO#	Note	Description	Qty	Sell		000 019299585			SPARK PLU	8 S	7.25	58.00	000 088862458		INSF	*WIRE KIT	1	126.99	126.99	Tech 207 HABIGER, JAY									
Part Number	PO#	Note	Description	Qty	Sell																											
000 019299585			SPARK PLU	8 S	7.25	58.00																										
000 088862458		INSF	*WIRE KIT	1	126.99	126.99																										
Tech 207 HABIGER, JAY																																
Type: C			Subtotal																													
			PARTS	184.99																												
			LABOR-MECHANICAL	189.99																												
			TOTAL CHARGE FOR CONCERN	374.98																												
Concern 55	CUSTOMER STATES THE CLIPS FOR THE SUN VISOR ARE LOOSE	Operation	Tech	Amount																												

Adv: 107 MARK WILSON	Tag M231	License GMW 4597	1G1YY22G7 25134231	Page 3	Invoice C15438
----------------------	-----------------	-------------------------	---------------------------	--------	-----------------------

Invoice to: CAMPBELL, BERNARD	Driver/Owner: CAMPBELL, BERNARD
--------------------------------------	----------------------------------------

Invoiced: 02/03/16 15:01:28 MW	02 CHEVROLET CORVETTE 2DR CPE BLUE
--------------------------------	------------------------------------

55-1 Parts Type: C	P/A DRIVERS AND PASSENGERS SUNSHADE RETAINERS/HOLDERS	207	29.99
	Part Number PO# Note Description Qty Sell		
	000 010411051 RETAINER	2	4.68 9.36
	Tech 207 HABIGER, JAY		
		Subtotal	
		PARTS	9.36
		LABOR-MECHANICAL	29.99
		TOTAL CHARGE FOR CONCERN	39.35
Concern 56 Type: C	CUSTOMER STATES THE DRIVERS SIDE SEAT BELT WONT RETRACT	Operation Tech	Amount
56-1	P/A DRIVERS SEAT BELT RETRACTOR	207	206.99
	Tech 207 HABIGER, JAY		
		Subtotal	
		LABOR-MECHANICAL	206.99
		TOTAL CHARGE FOR CONCERN	206.99
Concern 57 Parts Type: C	CUSTOMER STATES THE CHECK ENGINE LIGHT IS ON	Operation Tech	Amount
57-1	P/A BANK 2 SENSOR 2 OXYGEN SENSOR-CODE P0160	207	189.99
	Part Number PO# Note Description Qty Sell		
	000 019178933 INSF *SENSOR	1 S	125.94 125.94
	Tech 207 HABIGER, JAY		
		Subtotal	
		PARTS	125.94
		LABOR-MECHANICAL	189.99
		TOTAL CHARGE FOR CONCERN	315.93

Estimate of Charges for Estimate C15438	Payment Distribution for Invoice C15438
------------------------------------------------	------------------------------------------------

PARTS	974.72	TOTAL CHARGE	2813.19
SERVICE MATERIALS	50.00	CASH DUE	2813.19
LABOR-MECHANICAL	1703.93		
SUB-TOTAL	2728.65		
SALES TAX	84.54		
TOTAL CHARGE	2813.19		

WEB APP. LOANER; PLEASE QUOTE FOR DRIVERS SEATBELT REPAIR/REPLACE AND

Adv: 107 MARK WILSON	Tag M231	License GMW 4597	1G1YY22G7 25134231	Page 4 (Last)	Invoice C15438
----------------------	-----------------	-------------------------	---------------------------	---------------	-----------------------

Invoice to: CAMPBELL, BERNARD	Driver/Owner: CAMPBELL, BERNARD
--------------------------------------	----------------------------------------

Invoiced: 02/03/16 15:01:28 MW	02 CHEVROLET CORVETTE 2DR CPE BLUE
--------------------------------	------------------------------------

If you have any questions - please see MARK WILSON
WE CAME IN FIRST BECAUSE
WE NEVER LET OUR CUSTOMERS COME SECOND!