


Burned out Light.



Carefully separate the top portion from the bottom. The tabs can be easily broken.




Close up view of bulbs



Replacement bulb



Unsolder burnt out bulbs, and solder in new bulbs



Put pod back together again, and re-install gage cluster surround.