

#16-NA-247: Excessive Effort to Close Doors - (Aug 3, 2016)

Subject: Excessive Effort to Close Doors

Door weatherstrip is preventing door from closing/sealing completely - wind noise



| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|----------|-------------|------|------|----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Corvette | 2016 | 2016 | | | | |

| | |
|-----------------------------------|---|
| Involved Region or Country | North America and N.A. Export Regions |
| Condition | Some customers may comment on the doors requiring excessive effort to close. |
| Cause | This condition may be due to the increased pressure caused by the door weatherstrips. |

Correction

Once the condition has been duplicated and the door alignment has been checked, replace both door weatherstrips with the newly designed seals.

Service Procedure

Refer to *Front Side Door Weatherstrip Replacement* in SI.

Parts Information

| Description | Part Number | Qty |
|------------------------------------|-------------|-----|
| WEATHERSTRIP ASM-FRT S/D (DOOR SI) | 84008528 | 1 |
| | 84008529 | |

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor Operation | Description | Labor Time |
|--|---|------------|
| 1480718* | Replacing Both Front Door Weatherstrips | 0.9 hr |
| *This is a unique Labor Operation for Bulletin use only. | | |

| | |
|-----------------|---|
| Version | 1 |
| Modified | |

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your GM dealer for information on whether your vehicle may benefit from the information.



WE SUPPORT
VOLUNTARY
TECHNICIAN
CERTIFICATION