

# 16-NA-175: Shake And/Or Shudder During Light Throttle Acceleration Between 25 And 80 MPH (40 And 128 KM/H) At A Steady State – 2015-2018 Cadillac Chevrolet GMC



👤 [oemdtc](#) 📅 [May 15, 2018](#) 📖 [Diagnostic Tips](#)

#16-NA-175: Shake and/or Shudder During Light Throttle Acceleration Between 25 and 80 MPH (40 and 128 KM/H) at a Steady State – (Dec 13, 2017)

<b>Subject:</b>	Shake and/or Shudder During Light Throttle Acceleration Between 25 and 80 MPH (40 and 128 KM/H) at a Steady State
-----------------	---

Brand:	Model:	Model Year:		VIN Breakpoint		Engine:	Transmission:
		from	to	from	to		
Cadillac	GM Passenger Cars and Trucks	2015	2018	November 1, 2015	EOP	All	8L90 and 8L45 Automatic (RPOs M5U, M5T, M5N, M5X)
Chevrolet							
GMC							