

Invoice

Date	Invoice #
2/15/2012	2793

Bill to
 Gerald Jellema 702-426-0499

PAID



Year	Make	Model	Mileage	Vin #
1994	FORD	Mustang GT	186780	1FALP42T0RF229057
Quantity	Item Code	Description	Price Each	Amount
3	Diagnosis	Diagnose customer complaint Check drivetrain noise; completed inspection and diagnosis with chassis ear, noise appears to be coming from rear differential. Further inspection during teardown found gears to be set up incorrectly and also appears incorrect gears were installed per customers knowledge. Replace ring and pinion, replace all bearings and races with 3.55 gear set. Fuel lines are not safely routed, creating a potential fire hazard. Exhaust incorrectly installed, hanging too low and rubbing rear axle. Hydraulic clutch line is rubbing the steering shaft and also rubbing on the exhaust. Right rear tail light needs to be wired and routed correctly.	100.00	300.00
1	cup	Cup	17.60	17.60T
1	bearing	Bearing assembly	23.30	23.30T
1	cup	Cup	16.63	16.63T
1	cone	Cone	29.97	29.97T
1	bearing	Bearing assembly	23.30	23.30T
1	cup	Cup	14.97	14.97T
1	Seal	Seal assembly	20.73	20.73T
1	Spacers	Spacer	7.55	7.55T
1	bearing	Bearing assembly	33.77	33.77T
1	Seal	Seal	6.05	6.05T
7	Labor	Overhaul rear end	100.00	700.00
1	gear set	Ring and pinion set	445.43	445.43T
3	Differential fluid	Differential fluid	6.17	18.51T
1	Turn signal switch	Turn signal switch	83.11	83.11T
1.5	Labor	Diagnose, remove and replace turn signal switch	100.00	150.00
3	Labor	Remove and reinstall clutch line, move line away from heat sources, bleed clutch again	100.00	300.00
2	Brake Fluid	Brake Fluid	4.78	9.56T
Total				

Invoice

Date	Invoice #
2/15/2012	2793

Lf

Bill To

Gerald Jellema 702-426-0499

Your Dealership Service Alternative

Year	Make	Model	Mileage	Vin #	
1994	FORD	Mustang GT	186780	1FALP42T0RF229057	
Quantity	Item Code	Description	Price Each	Amount	
2	Labor	Reroute fuel lines	100.00	200.00	
1	Power steering flush	Perform power steering flush	125.00	125.00	
1	Brake Pad Set	Rear Brake Pad Set	89.98	89.98T	
2	Rotor	Rear rotors	66.63	133.26T	
2	Labor	Remove and replace rear pads and rotors	100.00	200.00	
2	Brake caliper	Rear brake calipers	177.70	355.40T	
2	Labor	Remove and replace both rear calipers, bleed brakes.	100.00	200.00	
0.5	Labor	Rewire and reinstall right rear tail light assembly	100.00	50.00	
		Sales Tax	8.10%	107.66	
			Total	\$3,661.78	