

**Fleet Service**

7511 Beverly Blvd  
 Everett, WA. 98203  
 Phone: 425-355-4440 Fax: 425-353-4799

Sub Estimate

**Estimate for Services**

Estimate Date : 1/30/2019

**Olson, Michael**

2002 Chevrolet - Corvette - 5.7L,V8 (350CI) VIN(G)

Lic # : - WA

Odom. In: 0

Cellular: 425-387-5505

VIN # :

| Part Description         | Qty  | Sale   | Ext    | Labor Description  | Extended |
|--------------------------|------|--------|--------|--|----------|
| Exh. Man. to Pipe Gasket | 1.00 | 33.13  | 33.13  | FLYWHEEL (STD TRANS) - Remove & Replace - All<br>Applicable Models - [Includes: R&I Exhaust System.] | 852.00   |
| Exhaust Pipe Gasket      | 1.00 | 35.04  | 35.04  |  |          |
| Exhaust Pipe Gasket      | 1.00 | 35.04  | 35.04  | Environmental  | 31.86    |
| Clutch Kit               | 1.00 | 622.30 | 622.30 |  |          |
| Misc. Extras             | 2.00 | 54.35  | 108.70 |  |          |
| Resurface Flywheel       | 1.00 | 75.99  | 75.99  |  |          |
| Shop Supplies            |      |        | 38.34  |  |          |

Parts/Supplies: 948.54      Labor: 852.00      HazMat/Fees: 31.86      Tax: 177.74      Total : \$ 2,010.14

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and /or your employees permission to operate the vehicle described for testing and/or inspection. Express mechanic's lien is hereby acknowledged on above vehicle to secure the amount of repairs thereto.

TEARDOWN ESTIMATE: I understand that my vehicle will be reassembled within \_\_\_days of the date shown above if I choose not to authorize the service recommended. All Parts removed will be discarded unless instructed otherwise: Save all Parts \_\_\_\_\_. NOT RESPONSIBLE FOR LOSS OR DAMAGE TO CARS OR ARTICLES LEFT IN CARS IN CASE OF FIRE, THEFT OR ANY OTHER CAUSE.

Signature \_\_\_\_\_ Date \_\_\_\_\_ Time \_\_\_\_\_