

BLACK	05	CHEVROLET CORVETTE	1G1YY24U855118501		24967/24994	T4435
IS DD DATE	PROD. DATE	WARR. EXP.	PROMISED	PO NO.	PAYMENT	INV. DATE
18MAR05 IS						
18MAR05 DD			17:30 10AUG18		CASH	13AUG18
R.O. OPENED		READY		OPTIONS: DLR:04564 ENG:6.0_Liter_SFI,_Alum		
10:39 10AUG18		09:17 13AUG18				

LINE	OPCODE	TECH	TYPE	HOURS	LIST	NET	TOTAL
------	--------	------	------	-------	------	-----	-------

A SES LIGHT IS ON, SERVICE TRACTION CONTROL MESSAGE COMES ON, REDUCED ENGINE POWER. CUSTOMER WAS ADVISED OF POSSIBLE BULLETINS.
 NC NO CHARGE TO OWNER FOR THIS REPAIR

3710 C 0.00 0.00

24994

-FOUND ENGINE STARTS AND RUNS NORMALLY-NO WARNING MESSAGES WERE ILLUMINATED ON IPC-CONNECTED TECH2 TO VEHICLE AND FOUND HISTORY ECM DTC P2135 THROTTLE POSITION SENSOR 1-2 CORRELATION
 -PERFORMED MULTIPLE THROTTLE BODY SWEEP TESTS, BUT FOUND BOTH SENSOR 1 AND 2 ALWAYS SHOW "AGREE"-ALSO FOUND BOTH TP SENSOR 1 AND 2 VARIATION LESS THAN 2% AT ALL THROTTLE INPUTS-DTC P2135 SET WHEN VEHICLE WAS GOING APPROX. 55mph AND THROTTLE INPUT NEAR 20%
 -ROAD TESTED VEHICLE 24967 TO 24994, BUT WAS UNABLE TO VERIFY CUSTOMER CONCERN (NO WARNING MESSAGES OR REDUCED ENGINE POWER CONDITION)
 -ADVISED SERVICE WRITER THAT CONCERN MAY BE INTERNAL TO THROTTLE BODY ITSELF, BUT IT IS UNKNOWN AT THIS TIME DUE TO INTERMITTENT NATURE OF CONCERN

B 20-POINT

MPVI 20-POINT

3710 INSP

(N/C)

INSPECTION PERFORMED LESS THAN 1K MILES AGO

C** TEST BATTERY GR8

BAT TEST BATTERY

3710 C

0.00 0.00

COMPLETED GR8 BATTERY DIAGNOSTIC

-FOUND BATTERY TESTS 578 CCA @ 12.91 VOLTS, INDICATING "GOOD BATTERY"

BATTERY"

-SUBMITTED COPY OF BATTERY TEST RESULTS TO BOTH SERVICE ADVISOR AND CUSTOMER
