

BEFORE MRCS UPGRADE

## GM Vehicle Calibration Information

<b>VIN:</b>	1G1YY3D73H5118944
<b>Controller:</b>	K19 Suspension Control Module
<b>Function:</b>	Programming
<b>Programming Type:</b>	Normal
<b>Vehicle Options:</b>	With Semi Active Damping System (RPO +FE2/FE4/FE6/FE7)

### Calibration History for: **Operating system**

Part Number	CVN	Bulletin #	Description
84213967	N/A	-	Updated Operating system
84059231	N/A	-	5.0 requires updates to version 6.0 to mitigate the potential for unintended damper short circuit faults (C0575, C0580, C0585, and C0590 with subtype byte \$1A)
23247866	N/A	-	Operating system

M4455: There are 2 calibration part numbers that are valid for 'Real Time Damping'. Read the descriptions from the following tables to determine the correct calibration for this vehicle.

### Calibration History for: **Real Time Damping**

Part Number	CVN	Bulletin #	Description
84168050	N/A	-	SADS Calibration Update
84136537	N/A	-	Real Time Damping

Part Number	CVN	Bulletin #	Description
84235322	N/A	-	Real Time Damping
84136537	N/A	-	Real Time Damping