

## 1956 to 1962 Corvette Windshield Post Tab Breakage and Repair

### Rich's Restoration Site Antique Automobile & Boat Restoration

[http://home.comcast.net/~richmz/site/?/page/1956 to 1962 Corvette Winshield Post Tab Breakage and Repair/](http://home.comcast.net/~richmz/site/?/page/1956%20to%201962%20Corvette%20Winshield%20Post%20Tab%20Breakage%20and%20Repair/)

While working on your windshield, if you discover your post tabs are broken, you must get them repaired before reassembly.

Below are 2 posts with broken post tabs. It may cause your header to pull away from the glass, especially when you try to attach a tight soft top while clamping down. Typically, when I restore a car, even if the tabs are not broken I send them out for steel replacements. The original castings are delicate and break easily. The replacements are much stronger.



## After repair:

As you can see, the tab is now permanently attached to the post and can be removed for post chrome plating or other work if needed.



Services are available to repair them.

My favorite supplier of this repair is Paul Mazut. His website is here:

[http://www.paulmazutcorvette.com/services/53\\_-62\\_windshield\\_post\\_tab.html](http://www.paulmazutcorvette.com/services/53_-62_windshield_post_tab.html)

RPM