



Bumper to Bumper Limited Warranty	06/23/2006	12 MI	06/23/2009	36,012 MI
Corrosion Limited Warranty	06/23/2006	12 MI	06/23/2012	100,012 MI
Emission Select Component Ltd Wty	06/23/2006	12 MI	06/23/2014	80,012 MI

## Service Contract

Vehicle has no current record of service contracts.

## Transaction History

[View Details](#)

Job Card Date	Job Card Number	Transaction Type	Transaction Adjustment	Labour Operation	Odometer Reading
09/12/2008	406029	ZREG----Regular Vehicle Transaction		F9709 - Drain and Refill Rear Axle Fluid	20,365 MI
09/12/2008	406029	ZREG----Regular Vehicle Transaction		Z5000 - DEALER/RETAILER TRADE(PART OBTAINED LOCALLY)	20,365 MI
07/03/2008	117949	ZREG----Regular Vehicle Transaction		B2298 - Roof Lift Off Panel Replacement	19,427 MI
07/03/2008	117949	ZREG----Regular Vehicle Transaction		Z5001 - VIP FREIGHT/POSTAGE REIMBURSEMENT	19,427 MI
01/17/2007	093499	ZREG----Regular Vehicle Transaction		N2120 - Front Side Door Handle Switch Replacement	7,852 MI
12/06/2006	091641	ZFAT----Field Action Recall		V1516 - 06041 - Inspect Roof - No Further Action Required (SMC Roof Already Installed)	6,300 MI
12/06/2006	091641	ZREG----Regular Vehicle Transaction		Y0110 - 06092 Customer Satisfaction Program - Owner Manual Update	6,300 MI
12/06/2006	091641	ZREG----Regular Vehicle Transaction		E2147 - Stabilizer Shaft Link Replacement - Both Sides	6,300 MI
05/04/2006	A27662	ZPDI----Pre-Delivery Inspection		Z7000 - Pre-Delivery Inspection - Base Time	0 MI

Global Warranty Management: [Site Map](#)

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.