

**INTERFACE WITH CUSTOMER**

## View Vehicle Transaction History Detail



This screen allows GMVIS users to view the available information on individual transaction for the VIN selected.

### Vehicle Information

VIN: 1G1YY26E365119188      Model: 1YY87-2006 CORVETTE Z06 2 DOOR  
 Service Contract: No      Branded Title: No      Warranty Block: No      PDI Status: No  
 Order Type: 70 - RETAIL - STOCK  
 Field Actions: [0 Open](#)      [REQUEST ANOTHER VIN](#)

**For this vehicle:**

- [View Vehicle Summary](#)
  - Service Contract
  - Branded Title
  - Warranty Block
- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)
- [Investigate Major Assembly History](#)

**Job Card Date:** 07/10/2007

**Job Card Number:** 343487

Repair Service Agent: 167909  
 RIVERSIDE CHEVROLET  
 707 W 51ST ST  
 TULSA OK 74107-8300  
 9184462200

Odometer Reading: 5,435 MI  
 Authorization Code: E

Process Date:  
07/31/2007

Transaction Type:  
ZREG---Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code:  
0000-Converted Claim

Job Card Line #: 1      Transaction Adjustment:      Cause Code: 0000-Converted Claims

Labour Op K0600-Cylinder, Actuator Clutch Master - R&R Or Replace

Causal Part Number

→ [See other Parts and/or Net Items](#)

**Job Card Date:** 07/10/2007

**Job Card Number:** 343487

Repair Service Agent: 167909  
 RIVERSIDE CHEVROLET  
 707 W 51ST ST  
 TULSA OK 74107-8300  
 9184462200

Odometer Reading: 5,435 MI  
 Authorization Code:

Process Date:  
07/31/2007

Transaction Type:  
ZREG---Regular Vehicle Transaction

Transaction Expense Category:

Customer Complaint Code:  
0000-Converted Claim

Job Card Line #: 2      Transaction Adjustment:      Cause Code: 0000-Converted Claims

Labour Op T2020-Towing

Causal Part Number

→ [See other Parts and/or Net Items](#)

**Job Card Date:** 07/10/2007

**Job Card Number:** 343487

Repair Service Agent: 167909

Odometer Reading: 5,435 MI

RIVERSIDE CHEVROLET  
707 W 51ST ST  
TULSA OK 74107-8300  
9184462200

Authorization Code:

---

Process Date:  
07/31/2007

Transaction Type:  
ZFAT----Field Action Recall

Transaction Expense Category:

Customer Complaint Code:  
0000-Converted Claim

Job Card Line #: 3                      Transaction Adjustment:                      Cause Code: 0000-Converted Claims

Labour Op V1495-06041- Inspect and Replace Roof (inc. 1.5 hrs for paint and mix time)

Causal Part Number

→ [See other Parts and/or Net Items](#)

---

---

**Job Card Date: 02/21/2006**

**Job Card Number: A19188**

Repair Service Agent: 207662

Odometer Reading: 0 MI

STONEBRIAR CHEVROLET  
9950 HIGHWAY 121  
FRISCO TX 75035-0000  
2144725500

Authorization Code:

---

Process Date:  
02/24/2006

Transaction Type:  
ZPDI----Pre-Delivery Inspection

Transaction Expense Category:

Customer Complaint Code:  
0000-Converted Claim

Job Card Line #: 1                      Transaction Adjustment:                      Cause Code: 0000-Converted Claims

Labour Op Z7000-Pre-Delivery Inspection - Base Time

Causal Part Number

---

Global Warranty Management: [Site Map](#)

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.