



Global Warranty Management: Main > Interface With Customer > View Vehicle Transaction History Detail

INTERFACE WITH
CUSTOMER

View Vehicle Transaction History Detail

This screen allows IVH users to view the available information on individual transaction for the VIN selected.

Vehicle Information

VIN: 1G1YT2D6XG5603645 Model: 1YZ07-2016 CORVETTE Z06 COUPE
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [Open](#) REQUEST ANOTHER VIN

For this vehicle:

- [View Vehicle Summary](#)
 - Service Contract
 - Branded Title
 - Warranty Block

- [View Vehicle Build](#)
- [View Vehicle Component Summary](#)
- [View Vehicle Transaction History Detail](#)
- [View Vehicle Delivery Information](#)

- [Investigate Major Assembly History](#)

Job Card Date: 03/19/2018 **Job Card Number:** 111610
 Repair Service Agent: 257951 Odometer Reading: 6,424 MI
 PLATINUM CHEVROLET Authorization Code: E
 3001 CORBY AVE
 SANTA ROSA CA 95407-7884
 7075251800

Process Date: 04/18/2018
 Transaction Type: ZREG—Regular Vehicle Transaction
 Transaction Expense Category: Warranty
 Customer Complaint Code: 0344-Transmission - Fluid Leaks
 Job Card Line #: 1 Transaction Adjustment: Cause Code: 6061-Module/Component - Leaks
 Labour Op 8441960-Reverse Gear Replacement
 Causal Part Number 00000000012523293-SEAL,MTRNS REV GR BLOCKOUT SOL (O-RIN)
 → [See other Parts and/or Net Items](#)

Job Card Date: 02/06/2018 **Job Card Number:** 110086
 Repair Service Agent: 257951 Odometer Reading: 6,182 MI
 PLATINUM CHEVROLET Authorization Code:
 3001 CORBY AVE
 SANTA ROSA CA 95407-7884
 7075251800

Process Date: 02/27/2018
 Transaction Type: ZREG—Regular Vehicle Transaction
 Transaction Expense Category: Warranty
 Customer Complaint Code: 0344-Transmission - Fluid Leaks
 Job Card Line #: 1 Transaction Adjustment: Cause Code: 6061-Module/Component - Leaks
 Labour Op 8442582-Extension Overhaul
 Causal Part Number 00000000024280393-GASKET-SHFT CONT HSG CVR
 → [See other Parts and/or Net Items](#)

Job Card Date: 02/14/2017 **Job Card Number:** 96793

6/5/2018

Global Warranty Management

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 3,774 MI
Authorization Code: E7N8

Process Date:
05/10/2017

Transaction Type:
ZREG—Regular Vehicle
Transaction

Transaction Expense
Category:
Warranty

Customer Complaint Code:
0344-Transmission - Fluid
Leaks

Job Card Line #: 1 Transaction Adjustment: Add Credit Cause Code: 4061-Interface (Gasket, Seal, Hose, Weld..) - Leaks

Labour Op 8442220-Transmission Adapter Replacement

Causal Part Number

→See other Parts and/or Net Items

Job Card Date: 02/14/2017

Job Card Number: 96793

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 3,774 MI
Authorization Code: E7N8

Process Date:
05/10/2017

Transaction Type:
ZREG—Regular Vehicle
Transaction

Transaction Expense
Category:
Warranty

Customer Complaint Code:
0344-Transmission - Fluid
Leaks

Job Card Line #: 1 Transaction Adjustment: Full Debit Cause Code: 4061-Interface (Gasket, Seal, Hose, Weld..) - Leaks

Labour Op 8442220-Transmission Adapter Replacement

Causal Part Number

→See other Parts and/or Net Items

Job Card Date: 02/14/2017

Job Card Number: 96793

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 3,774 MI
Authorization Code: E3N8

Process Date:
03/08/2017

Transaction Type:
ZREG—Regular Vehicle
Transaction

Transaction Expense Category:
Warranty

Customer Complaint Code:
0344-Transmission - Fluid

6/5/2018

Global Warranty Management

Leaks

Job Card Line #: 1 Transaction Adjustment: Cause Code: 4061-Interface (Gasket, Seal, Hose, Weld..) - Leaks

Labour Op 8442220-Transmission Adapter Replacement

Causal Part Number

→See other Parts and/or Net Items

Job Card Date: 01/16/2017

Job Card Number: 95634

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 3,680 MI
Authorization Code:

Process Date:
01/23/2017

Transaction Type:
ZREG---Regular Vehicle Transaction

Transaction Expense Category:
Warranty

Customer Complaint Code:
0021-No Customer Complaint - Maintenance

Job Card Line #: 4 Transaction Adjustment: Cause Code: 9098-Other - Maintenance

Labour Op 0600723-Chevrolet 2 Year Maintenance

Causal Part Number

→See other Parts and/or Net Items

Job Card Date: 01/16/2017

Job Card Number: 95634

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 3,680 MI
Authorization Code:

Process Date:
01/23/2017

Transaction Type:
ZFAT---Field Action Recall

Transaction Expense Category:
Field Action Recall

Customer Complaint Code:
-

Job Card Line #: 1 Transaction Adjustment: Cause Code: -

Labour Op 9102276-16007 - N16-204817 - Reprogram Inflatable Restraint Sensing and Diagnostic Module Calibrations

Causal Part Number

Job Card Date: 09/02/2016

Job Card Number: 90081

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 3,160 MI
Authorization Code:

Process Date:
09/28/2016

Transaction Type:
ZREG---Regular Vehicle Transaction

6/5/2018

Global Warranty Management

Transaction Expense Category:
Warranty

Customer Complaint Code:
0421-Exterior - Fit/Finish

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 3025-Rotating Part - Loose

Labour Op 2024270-Windshield Frame Weatherstrip Replacement

Causal Part Number 00000000023301533-WEATHERSTRIP ASM-W/S FRM

→See other Parts and/or Net Items

Job Card Date: 07/18/2016

Job Card Number: 88169

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 2,281 MI
Authorization Code:

Process Date:
07/26/2016

Transaction Type:
ZREG—Regular Vehicle
Transaction

Transaction Expense Category:
Warranty

Customer Complaint Code:
0344-Transmission - Fluid
Leaks

Job Card Line #: 1

Transaction Adjustment:

Cause Code: 4061-Interface (Gasket, Seal, Hose,
Weld..) - Leaks

Labour Op 8450010-Transmission Fluid Auxiliary Cooler Replacement

Causal Part Number

Job Card Date: 03/30/2016

Job Card Number: 83958

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 2,130 MI
Authorization Code:

Process Date:
03/31/2016

Transaction Type:
ZFAT—Field Action Recall

Transaction Expense Category:
Field Action Recall

Customer Complaint Code:
-

Job Card Line #: 6

Transaction Adjustment:

Cause Code: -

Labour Op 9102115-N150814 - Instrument Cluster Reprogramming with SPS

Causal Part Number

Job Card Date: 03/01/2016

Job Card Number: 82775

Repair Service Agent: 257951
PLATINUM CHEVROLET
3001 CORBY AVE
SANTA ROSA CA 95407-7884
7075251800

Odometer Reading: 1,684 MI
Authorization Code:

Process Date:
03/01/2016

Transaction Type:
 ZREG—Regular Vehicle Transaction
 Transaction Expense Category:
 Warranty
 Customer Complaint Code:
 0021-No Customer Complaint - Maintenance
 Job Card Line #: 1 Transaction Adjustment: Cause Code: 9098-Other - Maintenance
 Labour Op 0600723-Chevrolet 2 Year Maintenance
 Causal Part Number
 →See other Parts and/or Net Items

Job Card Date: 12/30/2015	Job Card Number: 80415
Repair Service Agent: 257951 PLATINUM CHEVROLET 3001 CORBY AVE SANTA ROSA CA 95407-7884 7075251800	Odometer Reading: 523 MI Authorization Code:

Process Date:
01/04/2016
 Transaction Type:
ZREG—Regular Vehicle Transaction
 Transaction Expense Category:
Warranty
 Customer Complaint Code:
0021-No Customer Complaint - Maintenance
 Job Card Line #: 1 Transaction Adjustment: Cause Code: 9098-Other - Maintenance
 Labour Op 0600723-Chevrolet 2 Year Maintenance
 Causal Part Number
 →See other Parts and/or Net Items

Job Card Date: 10/05/2015	Job Card Number: 94271
Repair Service Agent: 276295 WEST HERR CHEVROLET OF WILLIAMSVILL 8040 TRANSIT RD WILLIAMSVILLE NY 14221-4116 7166325110	Odometer Reading: 1 MI Authorization Code:

Process Date:
11/02/2015
 Transaction Type:
ZPDI—Pre-Delivery Inspection
 Transaction Expense Category:
Pre-Delivery Inspection
 Customer Complaint Code:
-
 Job Card Line #: 3 Transaction Adjustment: Cause Code: -
 Labour Op 0590052-PDI Related Fluid Adds
 Causal Part Number
 →See other Parts and/or Net Items

Job Card Date: 09/25/2015	Job Card Number: A03645
Repair Service Agent: 276295 WEST HERR CHEVROLET OF WILLIAMSVILL 8040 TRANSIT RD WILLIAMSVILLE NY 14221-4116 7166325110	Odometer Reading: 1 MI Authorization Code:

6/5/2018

Global Warranty Management

Process Date:
09/25/2015

Transaction Type:
ZPDI—Pre-Delivery Inspection

Transaction Expense Category:
Pre-Delivery Inspection

Customer Complaint Code:
-

Job Card Line #: 1

Transaction Adjustment:

Cause Code: -

Labour Op 0590072-Pre-Delivery Inspection - Base Time

Causal Part Number

Global Warranty Management: Site Map

[Privacy Policy](#) | [Terms of Use](#)

© 2005 General Motors. All rights reserved.